

Water Testing Results - High Desert ESD Skyliner Lodge

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Test Date	Test Result
North bathroom sink	8/17/2016	2
South bathroom sink	8/17/2016	ND
Large kitchen sink	8/17/2016	ND
Small kitchen sink	8/17/2016	ND
West FP hydrant	8/17/2016	104
South FP hydrant	8/17/2016	2
Boys FP hydrant	8/17/2016	ND
Girls FP hydrant	8/17/2016	ND
Parking FP hydrant	8/17/2016	ND
West FP hydrant	9/22/2016	5

ND = Non Detect - Lead level is below the set detection limit of 2 ppb