

Radon test result report for:**AHC**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7203657	101	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	4.3 ± 0.4	2018-04-20
7203659	101	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7203663	102	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7203665	103	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205049	104	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205048	105	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205047	106	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205046	107	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7203662	108	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7203661	109	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205045	110	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205044	111	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7203660	112	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205043	113	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205050	114	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	0.5 ± 0.2	2018-04-20
7205051	114	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205042	114	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7205041	115	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20
7203664	116	2018-04-16 @ 1:00 pm	2018-04-19 @ 8:00 am	< 0.3	2018-04-20