

Kit Number	Start Date	Start Time	End Date	End Time	Temperature	Facility	Building	Room	Project ID	Floor	Result	Variance	Analysis No	Analysis Date	%Moisture
7203657	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	101		3	4.3	0.4		2018-04-20	12.8
7203659	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	101		3	< 0.3	0.2		2018-04-20	5.2
7203660	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	112		3	< 0.3	0.2		2018-04-20	5.2
7203661	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	109		3	< 0.3	0.2		2018-04-20	4.4
7203662	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	108		3	< 0.3	0.2		2018-04-20	3.6
7203663	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	102		3	< 0.3	0.2		2018-04-20	5.2
7203664	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	116		3	< 0.3	0.2		2018-04-20	3.6
7203665	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	103		3	< 0.3	0.2		2018-04-20	3.6
7205041	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	115		3	< 0.3	0.2		2018-04-20	3.6
7205042	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	114		3	< 0.3	0.2		2018-04-20	4.4
7205043	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	113		3	< 0.3	0.2		2018-04-20	4.4
7205044	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	111		3	< 0.3	0.2		2018-04-20	4.4
7205045	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	110		3	< 0.3	0.2		2018-04-20	3.6
7205046	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	107		3	< 0.3	0.2		2018-04-20	4.4
7205047	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	106		3	< 0.3	0.2		2018-04-20	3.6
7205048	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	105		3	< 0.3	0.2		2018-04-20	3.6
7205049	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	104		3	< 0.3	0.2		2018-04-20	4.4
7205050	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	114		3	0.5	0.2		2018-04-20	3.6
7205051	2018-04-16	1:00 pm	2018-04-16	8:00 am	70		AHC	114		3	< 0.3	0.2		2018-04-20	3.6