

Radon test result report for:

PEC

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7137603		2016-11-14 @ 9:00 am	2016-11-17 @ 10:00 am	< 0.3	2016-11-21
7137623		2016-11-11 @ 10:00 am	2016-11-14 @ 10:00 am	29.3 ± 2.2	2016-11-21
7137618		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.8 ± 0.3	2016-11-21
7137613		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.8 ± 0.3	2016-11-21
7137606		2016-11-14 @ 9:00 am	2016-11-17 @ 10:00 am	0.7 ± 0.3	2016-11-21
7137624		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	< 0.3	2016-11-21
7137619		2016-11-14 @ 9:00 am	2016-11-17 @ 10:00 am	0.8 ± 0.3	2016-11-21
7137614		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.6 ± 0.3	2016-11-21
7137608		2016-11-14 @ 9:00 am	2016-11-17 @ 10:00 am	0.8 ± 0.3	2016-11-21
7137625		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.6 ± 0.3	2016-11-21
7137620		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.6 ± 0.3	2016-11-21
7137615		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.8 ± 0.3	2016-11-21
7137610		2016-11-14 @ 9:00 am	2016-11-17 @ 10:00 am	0.9 ± 0.3	2016-11-21
7137626		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.6 ± 0.3	2016-11-21
7137621		2016-11-14 @ 9:00 am	2016-11-17 @ 10:00 am	0.6 ± 0.3	2016-11-21
7137616		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.6 ± 0.3	2016-11-21
7137611		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.7 ± 0.3	2016-11-21
7137627		2016-11-14 @ 9:00 am	2016-11-17 @ 10:00 am	0.5 ± 0.3	2016-11-21
7137602		2016-11-14 @ 9:00 am	2016-11-17 @ 10:00 am	0.9 ± 0.3	2016-11-21
7137622		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	0.8 ± 0.3	2016-11-21
7137617		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	1.0 ± 0.4	2016-11-21
7137612		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	1.0 ± 0.3	2016-11-21
7137628		2016-11-14 @ 8:00 am	2016-11-17 @ 10:00 am	< 0.3	2016-11-21